


## 異常検知が発生



平成22年10月2日(土)17時00分 定時測定(5V測定)

	D11	D12	D13	D14	D15	D16	D17	D18	D19	D20	D21	D22	D23	D24	D25
U16													0.03		0.02
U17	0.03	0.03	0.00	0.00									0.00		0.00
U18	0.11	0.10	0.09	0.13									0.11		0.13
U19	0.00	0.00	0.00	0.01									0.01		0.00
U20	0.01	0.03	0.05	0.14							16.44		0.12		0.03
U21	0.05	0.09	0.11	0.40							49.79		0.40		0.05
U22		0.28	0.44	17.33							49.79		17.27		0.44
U23			0.03												
U24			0.07	0.42							49.79		0.41		0.16
U25			0.09	0.40							49.79		0.37		0.13
U26			0.07	0.33							41.70		0.32		0.09
U27			0.09	0.21							24.60		0.21		0.07
U28			0.06	0.21							25.74		0.23		0.07
U29			0.06	0.16							16.57		0.17		0.07
U30			0.05	0.10							0.04		0.03		0.03
U31			0.03	0.02							0.03		0.03		0.03
U32			0.03	0.02							0.03		0.03		0.03
U33			0.05	0.04							0.05		0.05		0.05
U34			0.12	0.12							0.15		0.15		0.15
U35			0.07	0.05							0.05		0.04		0.04
U36			0.06	0.05							0.05		0.04		0.03
U37			0.06	0.05							0.04		0.04		0.03
U38			0.08	0.07							0.06		0.05		0.04
U39			0.08	0.08							0.07		0.05		0.05
U40			0.05	0.05							0.05		0.04		0.04
U41			0.03	0.02							0.03		0.02		0.01
U42			0.03	0.03							0.06		0.04		0.01
U43			0.03	0.04							0.06		0.05		
U44			0.03	0.03											
U45			0.02	0.03							0.02				
U46			0.07	0.09					0.12	0.09	0.11	0.07	0.06	0.05	0.02
U47			0.05	0.10	0.05			0.00	0.18	0.14	0.16	0.10	0.05	0.07	0.01
U48			0.00	0.04	0.02			0.12	0.10	0.06	0.02	0.03	0.00	0.03	0.00
U49			0.00	0.04	0.02			0.05	0.04	0.03	0.00	0.03	0.01	0.02	0.00
U50			0.05	0.09	0.06	0.03	0.03	0.05	0.07	0.07	0.09	0.11	0.05	0.04	0.03
U51			0.00	0.00	0.00	0.00	0.01	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
U52			0.21	0.25	0.06	0.06	0.13	0.15	0.10	0.11	0.29	0.07	0.29	0.07	0.31
U53							0.00	0.02	0.00	0.00	0.00	0.00	0.00	0.00	0.00
U54							0.03	0.08	0.06	0.05	0.12	0.04	0.11	0.03	0.11
U55							0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00	0.00
U56											0.00	0.00	0.00	0.00	0.00
U57															
U58															
U59															
U60															
U61															
U62								0.07	0.07	0.07	0.18	0.05	0.17	0.05	0.19

※測定結果がない箇所は、埋立地の構造上存在しない銅線電極交点。

平成22年10月2日(土)17時00分 定時測定(5V測定)(異相分)