


異常検知継続中



平成22年10月4日(月)9時00分 定時測定(5V測定)

	D11	D12	D13	D14	D15	D16	D17	D18	D19	D20	D21	D22	D23	D24	D25	
U16													0.03		0.02	
U17	0.04	0.04	0.00	0.00									0.00		0.00	
U18	0.11	0.12	0.10	0.15									0.12		0.13	
U19	0.00	0.01	0.01	0.03									0.01		0.00	
U20	0.01	0.03	0.04	0.12							13.42		0.10		0.02	
U21	0.05	0.10	0.11	0.36							49.79		0.39		0.12	
U22		0.28	0.45	17.87							49.79		18.06		0.47	
U23			0.04													
U24			0.07	0.41							49.79		0.44		0.16	
U25			0.08	0.38							49.79		0.39		0.13	
U26			0.07	0.25							39.75		0.31		0.09	
U27			0.09	0.21							24.01		0.22		0.07	
U28			0.07	0.21							25.98		0.23		0.07	
U29			0.07	0.16							16.59		0.17		0.07	
U30			0.05	0.10							10.59		0.11		0.04	
U31			0.03	0.08							6.80		0.09		0.03	
U32			0.03	0.07							4.09		0.09		0.04	
U33			0.06	0.09							1.91		0.09		0.05	
U34			0.12	0.18							2.69		0.21		0.15	
U35			0.07	0.07							0.46		0.06		0.04	
U36			0.06	0.07							0.40		0.05		0.04	
U37			0.06	0.07							0.39		0.05		0.04	
U38			0.08	0.08							0.40		0.07		0.05	
U39			0.08	0.08							0.36		0.06		0.05	
U40			0.05	0.05							0.30		0.05		0.04	
U41			0.02	0.03							0.31		0.03		0.01	
U42			0.03	0.04							0.32		0.05		0.01	
U43			0.03	0.04							0.24		0.05			
U44			0.03	0.03												
U45			0.02	0.03							0.19					
U46			0.06	0.12						0.13	0.10	2.11	0.08	0.10	0.05	0.02
U47			0.06	0.14	0.05				0.00	0.22	0.16	2.42	0.11	0.10	0.07	0.02
U48			0.00	0.05	0.03				0.14	0.11	0.07	0.46	0.04	0.02	0.03	0.00
U49			0.00	0.05	0.02				0.06	0.05	0.04	0.29	0.03	0.02	0.02	0.00
U50			0.04	0.09	0.06	0.04	0.03	0.06	0.09	0.10	0.28	0.12	0.08	0.06	0.04	
U51			0.00	0.00	0.00	0.00	0.01	0.00	0.00	0.00	0.26	0.00	0.00	0.00	0.00	
U52			0.28	0.32	0.08	0.08	0.15	0.18	0.12	0.12	0.36	0.09	0.32	0.08	0.33	
U53								0.00	0.03	0.00	0.00	0.04	0.00	0.00	0.00	
U54								0.03	0.10	0.06	0.06	0.25	0.04	0.13	0.03	0.13
U55								0.00	0.00	0.00	0.04	0.00	0.00	0.00	0.00	
U56											0.02	0.00	0.00	0.00	0.00	
U57																
U58																
U59																
U60																
U61																
U62								0.08	0.07	0.07	0.32	0.06	0.20	0.05	0.21	

※測定結果がない箇所は、埋立地の構造上存在しない銅線電極交点。

平成22年10月4日(月)9時00分 定時測定(5V測定)(署相分)